"Documento original en mal estado"




FIGURE 3 143. Filing cabinets \$\frac{3}{2}\$ properly detailed as these are, will not present a problem in the event of an earthquake. Photograph courtesy \$\frac{4}{2}\$ Ruhnan Evans Ruhnan Associates

## REFERENCE FIGURES FOR INSTALLATION DETAILS

4.108, 4.109

RELATIVE DEGREE OF DAMAGE OF INADEQUATELY PROTECTED FQUIPMENT

Minor.

MOST LIKELY TYPE OR CONSEQUENCY OF PAMAGE FOR INADEQUATELY PROTECTED EQUIPMENT

- Toppled filing cabinets.
- General cleanup required.
- Potential for personnel injury

REFERENCE FIGURES FOR EXAMPLES OF DAMAGED FORPMENT

• 3.194, 3.195, 3.196.

## Miscellaneous Equipment

Monttors, CRT

CR1 monitors (Figure 3.144) should be installed per manufacturer recommendations




FIGURE 3.144. These unsecured CRT monitors have been installed on a shelf that is designed for one set. Note that they are sitting on a thin board because they were too large for the shelf.

### EQUIPMENT SFISMIC CATEGORY

• "C" support equipment

## SEISMIC SPECIFICATION

• SDS-2

SEISMIC QUALIFICATION APPROACH

- Equivalent static coefficient analysis.
  - · Bracket anchorage to wall
  - · CRT anchorage to bracket.
- Dynamic analysis
  - Manufacturers may wish to perform generic qualification programs for mounting monitors on their brackets.

## BEFERENCE FIGURE FOR INSTALLATION DETAILS

**4.67**.

BLATIVE DEGREE OF DAMAGE OF INADEQUATELY PROTECTED EQUIPMENT

Minor to moderate.

MOST LIKELY TYPE OR CONSEQUENCE OF DAMAGE FOR NADEQUATELY PROTECTED EQUIPMENT

- Toppled CRTs.
- Inoperative equipment
- Potential for personnel injury.
- · General cleanup required

INTERENCE FIGURE FOR EXAMPLE OF DAMAGED EQUIPMENT

• 3.172.

## Miscellaneous Equipment

## Personnel Lockers

These items need anchorage to prevent toppling (Figure 3.145).

## EQUIPMENT SEISMIC CATEGORY

• "E" miscellaneous equipment.

### SEISMIC SPECIFICATION

SDS-2.

## SEISMIC QUALIFICATION APPROACH

- Equivalent static coefficient analysis
  - · Base anchorage
  - · Attach to walls where possible.
  - · Braced tops

## REFERENCE FIGURES FOR INSTALLATION DETAILS


• 4 108, 4 109

## RELATIVE DEGREE OF DAMAGE OF INADPQUALELY PROTECTED EQUIPMENT

Minor to moderate.

# MOST LIKELY TYPE OR CONSEQUENCE OF DAMAGE FOR INADEQUATELY PROTECTED EQUIPMENT

- Toppled lockers.
- General cleanup required.



HIGURE 3.145 An example of personnel lockers that have been properly installed. They we have anchored at regular intervals to their foundation.

## Miscellaneous Equipment

Storage, Ad Hoc

Ad hoc storage (Figure 3.146) generally does not fare well during an earthquake.

## EQUIPMENT SEISMIC CALLGORY

• "E" miscellaneous equipment.

## SEISMIC SPECIFICATION

• SDS-2.

## SISMIC QUALIFICATION APPROACH

• Design team judgment.

## REFERENCE FIGURES FOR INSTALLATION DETAILS

4.102, 4.103, 4.104.

# MELATIVE DEGREE OF DAMAGE OF INADEQUATELY PROTECTED EQUIPMENT


Minor to moderate

# MOST LIKELY TYPE OR CONSEQUENCE OF DAMAGE FOR MADEQUATELY PROTECTED EQUIPMENT

- Toppled storage
- Spilled shelf contents.
- General cleanup required.

# MIERENCE FIGURE FOR EXAMPLE OF DAMAGED EQUIPMENT

3.197.



**TIGURE 3.146.** Example of ad hoc storage that is akely to collapse duting an earthquake,

## Miscellaneous Equipment

Storage Shelves

General storage shelves (Figure 3 147) must be considered with respect to the shelving as well as the shelf contents.

### FOURMENT SEISMIC CATEGORY

• "I miscellaneous equipment

#### SLISMIC SPECIFICATION

SDS-2.

### SLISMIC QUALIFICATION APPROACH

- Equivalent static coefficient analysis.
  - · Base unchorage
  - · Top bracing and anchorage.
- Design team judgment.
  - Provide shelved item restrainers.

### REFERENCE FIGURES FOR INSTALLATION DETAILS

4 53, 4, 54, 4 55, 4 56, 4 102, 4, 103, 4, 104.

## RELATIVE DEGREE OF DAMAGE OF INADEQUATELY PROTECTED EQUIPMENT

Minor to moderate.

# MOST LIKELY TYPE OR CONSEQUENCE OF DAMAGE FOR INADEQUATED PROTECTED EQUIPMENT.

- Shelf units topple.
- Items fall from shelves.
- General cleanup required

# REFERENCE FIGURES FOR EXAMPLES OF DAMAGED EQUIPMENT

• 3 191, 3,192, 3 193, 3 198




FIGURE 3.147. General storage shelps such as those shown here require base anchorage longitudinal bracing no bracing and shell parapets. This shelps must have not received any of the protection.

## Miscellaneous Equipment

## Typewriters

Although typewriters are not necessary for the operation of any facility, they do pose a threat to facility personnel if they fall and can add to the general cleanup required if they are not considered.

#### EDDIPMENT SLISMIC CATEGORY

"E" miscellancous equipment.

## SEISMIC SPECIFICATION

♦ SDS-2.

## SEISMIC QUALIFICATION APPROACH

- · Design team judgment.
  - Anchor to desk.
  - Provide lips on desk to prevent their sliding off.

## REFERENCE FIGURE FOR INSTALLATION DETAILS

4.110

## MELATIVE DEGREE OF DAMAGE OF INADI QUATELY PROTECTED EQUIPMENT

• Minor.

### MOST LIKELY TYPE OR CONSEQUENCE OF DAMAGE FOR

NADEQUATELY PROTECTED EQUIPMENT

- General cleanup required
- Possibility for personnel anjury.

# EXAMPLES OF DAMAGED EQUIPMENT

This section is included to illustrate the potential for damage to equipment by an earthquake. The preceding section of this chapter contains references to this section under the individual equipment items wherever possible.

All the example damage photographs are of equipment failures that resulted from one of three Southern California earthquakes, the San Fernando earthquake (1971, M 6 6), the Santa Barbara earthquake (1978, M 5.1), and the Imperial County earthquake (1979, M 6.6). The reader will note that these are relatively moderate earthquakes and yet the damage in many cases is quite striking. A larger magnitude earthquake produces the same types of damage, only over a larger area.

A thorough study of these photographs will give the designer, manufacturer, facility owner, and so on a much clearer picture of what to expect if

240

building equipment is not adequately protected. These photographs address the structural integrity of equipment rather than its operational capabilities. Equipment that must remain operational may look good after an earthquake, but because of internal failures or support equipment tailures may be completely inoperable. This concept must be borne in mind, especially when dealing with critical equipment.

It is hoped that the review of these photographs will underscore the importance of seismic qualification programs for all types of equipment, not just selected items that are specifically required by building codes. Designers and manufacturers have the opportunity to use this section on new facilities, while facility owners can use it as a checklist on walk-through tours of their existing buildings to improve the chance for survival of their equipment. Many existing facilities desperately need such backlitting programs even if they are not required by the existing codes.

The author wishes to apologize for the quality of some of the photograpts contained in this section. They have been taken from various sources and it some cases the originals could not be located, which necessitated copying them directly from the original publication, a less than desirable procedure. It was felt, however, that the points that they illustrate are important enough to justify their reproduction




FIGURE 3-148. An erill that disloged and fell. Positive attachment and a safety wire would have prevented this potentially dangerous, an atom. Photograph countery of Richard Miller and the National Science Confidence.

CHGA RE 3.149. Separation of ar plenum as viewed from inside the dusing. Photograph courtesy of Richard Miller and the National Science Founda-




FIGURE 3 150. Damage to wall where inadequately restrained ducing pounded during the earthquake. This photograph inustrates the need for separating equipment that could coilide Joring an earthquake with the potential for damage to critical equipment by support equipment. Photograph courtesy of Richard Miller and the National Science Foundation.




FIGURE 3.151. Unrestrained air handling unit slab that shifted. These slabs must be restrained if the equipment they support is to remain operational. Photograph courtesy of Richard Miller and the National Science Foundation.