



FIGURE 6-4 Crushing Failure In A 72"φ 'Lock Joint' Pipe,
1985 Michoacan Earthquake