



FIGURE 6-17 Break Near Joint Of An Asbestos Cement Pipe, 1985 Michoacan Earthquake