



Photo 4.35 Basilica of Our Lady of Charity at Agoa, built as r.c. structure, damaged. Strengthening of the r.c. columns with jackets through foundations and new arches for increase of stiffness in the longitudinal direction.



Photo 4.36 Damaged brick masonry - Church of Dagupan. The church was in poor structural conditions prior to the earthquake with extensive settlement cracks.




Photo 4.37 Front plate at the Church of Dagupan damaged and repaired after the earthquake of 1892.