



Small, well-maintained homes are representative of the housing in the special studies zones in Hollister (Photographs 40 and 41). Photograph 40, however, shows extensive structural damage to the walls and sidewalks.

