



Fig. 6 (a) Collapse of a precast-concrete frame structure due to failure of poorly-connected precast elements




Fig. 6 (b) Failure of column-splice due to poor detailing and workmanship of ties and welding of main bars

Fig. 6 ILLUSTRATION OF DAMAGE TO A PRECAST CONCRETE FRAME BUILDING DUE TO POOR DETAILING AND WORKMANSHIP (EERI SLIDE LIBRARY)