



Photo 3 Buckled pavement




Photo 4 Damage to outlet tunnel (provided by Tohoku Electric Power Company)




Photo 5 Damage to open aqueduct



Photo 6 Basalt rock that appeared on a failure surface




Photo 7 Basalt rock layer sandwiched in between loamy soils