




FIGURE 70.—Severe damage to flat beams and slab in the five-story reinforced-concrete Edificio ELGIN, in Guatemala City (Zone 14).