

FIGURE 57.—Collapse of an elevated steel water tank in the Instituto Técnico Vocacional in Guatemala City (Zone 13).




FIGURE 58.—Engineering plans of an elevated water tank shown in figure 59.
(ϕ , diameter.)