

FIGURE 59.—Collapse of an elevated steel water tank in Villanueva, Colonia de los Planes, 22 km south of Guatemala City.



FIGURE 60.—Collapse of a corrugated-steel grain silo in Villalobos, 5 km southeast of Guatemala City




FIGURE 61.—Plan of sedimentation tank and Plant Lo de Coy of the XAYA-PIXCAYA project and cracks (heavy lines) running under and across the sedimentation tank.

FIGURE 62.—Severe damage to reinforced-masonry construction caused by secondary faulting in Colonia San Francisco (Zone 19). The fault strikes north to northeast.

