



FIGURE 67.—Partial collapse of protruding first-story structure of the Cruz Azul 11-story reinforced-concrete building caused by falling (shown by arrows) of masonry walls from the two topmost stories, in Guatemala City (Zone 1).



FIGURE 68.—Collapse of one-story reinforced-concrete framed structure in the Licorera Mixco, Mixco.