



Fig. 7.29 Diagonal cracks in east-west shear wall in first story of Engineering Building, UCSB.



Fig. 7.30 Cracks in another portion of the north-south shear wall in the first story of Engineering Building, UCSB.