



Fig. 7.33 Diagonal crack in north-south shear wall in third story of Engineering Building, UCSB.



Fig. 7.34 Biological Science II Building, UCSB, (View from northeast).