




**Fig. 7.39** Pattern of X cracks in 10 inch thick R/C shear wall at east end of first story of Administration Building, Delco Electronics facilities.



**Fig. 7.40** Pattern of X cracks in shear wall at west end in first story of Administration Building, Delco Electronics facilities.