

Fig. 7.41

Diagonal crack in shear wall near center stair tower in second story of Administration Building, Delco Electronics facilities.




Fig. 7.42

Cracks in shear wall over doorway at west end in first story of Administration Building, Delco Electronics facilities.