



Fig. 7.45

Cracks at joints between panels and doors, Research and Development Building, Delco Electronics facilities.



Fig. 7.46

Cracking and spalling of columns at southwest corner of Research and Development Building, Delco Electronics facilities.