



Fig. 7.50 Cracks in exterior plaster walls of two story residential building in Isla Vista.



Fig. 7.51 Cracks in exterior plaster walls of two story residential building in Isla Vista.