



Fig. 7.60

Air traffic control tower, Santa Barbara Municipal Airport (view from south).




Fig. 7.61

Damage to joint between steel bracing tube and column in southeast corner, second story, air traffic control tower. Damaged tube runs north and south.