



Figure 7.66 Interior of large hangar at facilities of Aero Spacelines, Inc., showing large sliding doors and damaged steel bracing which angles up to the roof from the rail at top of doors



Figure 7.67 Close up from directly under damaged steel bracing of sliding doors shown in Fig. 7.66. Note separation of rail and bracing in center of picture

## 7.6 Acknowledgments

The willingness of many individuals and organizations to provide tours of damaged facilities, photographs, damage reports, and similar assistance is gratefully acknowledged. The long list of such individuals includes especially Mr. Stanley H. Mendes, consulting structural engineer, Mr. John F. Meehen and Mr. Donald Jephcott and their associates with the Office of the State Architect, Mr. Ray Nokes with the County of Santa Barbara, Mr. Charles Drier and Mrs. Clare Bailey with the City of Santa Barbara, the staffs of the Facilities Management and Environmental Health and Safety Departments at UCSB, Mr. Thomas Steiglitz with Delco Electronics, and Mr. Kirk S. Irwin, President of Aero Spacelines, Inc.