

Fig. 8.18 Broken cast-iron valve at discharge connection of pump on top of six-story Ellison Hall, UCSB.




Fig. 8.19 Break in 8 inch sea water discharge pipe at wall penetration, UCSB Marine Research Facility.