

Fig. 8.12 Boiler on top of six-story Ellison Hall, UCSB. Vibration isolation supports were damaged.




Fig. 8.13 Close up of damaged support on left side of boiler (Fig. 8.12).