

Fig. 8.14 Boiler on top of six-story Phelps Hall, UCSB. Vibration isolation supports were not damaged.




Fig. 8.15 Overhead close up of seismic restraint on boiler (Fig. 8.14).