



Fig. 11.5 Damage to seismic joints on third through sixth floor walkways between South Hall and the Graduate Tower, UCSB campus.




Fig. 11.6 Close up of damage to seismic joints shown in Fig. 11.5. View from inside walkway.