



Figure 6: Settlements of up to 18 inches disrupted the surface drainage at the commercial port facilities



Figure 7: Lateral movement and cracking of the pavement, commercial port facilities