



Figure 10: Aerial view of the Piti Electric Power Plant



Figure 11: Leaning of the power poles caused by lateral spreading at the Piti Electric Power Plant