



Fig. 6 Discoloration of Support Columns Indicates That Two CVTs Have Failed.




Fig. 7 Rope Used As Temporary Replacement for Damage Hardware