



PHOTO 15 Corrosion spots on fence in the emergency stairway




PHOTO 16 Corrosion spots along the steel column in the emergency stairway