



Photo 21 - External wall of the Hospital

Note the crack at the corner.

It would have been preferable to have a separation joint at this corner location.




Photo 22 - Informal entrance to the underside of the lowest floor of the Hospital
Conditions for maintenance repair and replacement of services are too difficult.