



Photo 41. One-way avenue to the East of the site. A drainage grille combined with a fine mesh to collect debris is used for stormwater drainage.



Photo 42. Drainage grille with mesh blocked with silt.



Photo 43. Car park adjacent to the South Block. The mesh in this drain is blocked with silt.