




Photo 5. The Inflammable Store, between Physiotherapy and the Maintenance Store.



Photo 6. Workshop #1 as seen from the North-East.



Photo 7. Small shed on the North end of Workshop #1. The workmanship of the horizontal courses of the mortar joints between blocks is poor.




Photo 8. Splitting of the timber along the grain at the support of a roof truss in Workshop #1.