



Photo 9. A view of Workshop #2 from the East. Flooding of both workshops due to stormwater flow behind this building from the Boiler House area has been reported.



Photo 10. The Physiotherapy Department and Chapel, as seen from River Road to the South.



Photo 11. A view of the entrance of the Physiotherapy Department.



Photo 12. A long, diagonal crack at the upper North-East corner of the Physiotherapy Department. This crack continues along the East perimeter wall at the same level.