




Photo 13. The Boiler House, as seen from the North.




Photo 15. The roof of the Boiler House has been reported to be leaking.




Photo 14. A long vertical crack in the Southern corner column of the Boiler House.




Photo 16. The hooked bolt detail used in both the Boiler House and the Laundry House to tie the roof sheets to the purlins. This detail is inadequate for hurricane resistance.