



Photo 17. A partial view of the Laundry House from the West.




Photo 19. The Maintenance Store as seen from the North-West. The gate closes off the covered link between this building and the Linen Supply Store.



Photo 18. Extensive damage to blockwork in the East wall of the Laundry House.




Photo 20. The close proximity of the Linen Supply Store and the Maintenance Store, coupled with the covered link, makes them appear to make up one building.