



Photo 33. View towards River Road to the West, from the access on the West boundary.



Photo 34. A pedestrian access to the Hospital, leading to the South Block from River Road.



Photo 35. An example of junction cracking in the walls. The interface of structural elements and the infill clay brick wall is clearly delineated by these cracks.



Photo 36. Damage to the soffit of an SB Slab in the South Block. The brittle nature of fired clay results in the unexpected collapse of broken portions of clay 'pots'.