



Photo 7 - Main entrance
Low-lying and poorly drained



Photo 8 - Side entrance
Wind-driven rain leaks through the windows