



Photo 9: Official entrance to hospital. Note narrow driveway. Bridge in background.



Photo 10: Underside of bridge. Steel truss similar to that shown here is recommended at eaves level for horizontal stability.



Photo 11: Front view of operating theatre. Note limited parking area in hospital yard.




Photo 12: Close-up of operating theatre windows. Timber roof protects out-of-use air-conditioning equipment housed on reinforced concrete sub-roof.