







9. Former doctor's residence on the north-west side of the site.




10. A view of one end of the L-Block. Note the steeply sloped hipped roof - good for hurricane resistance.




11. Another view of the L-Block. Note the dormer windows.




12. Further evidence of lack of maintenance - grass growing on a verandah roof on the L-Block. Note also the rusting corrugated sheets on the kitchen roof in the foreground.




13. Typical roof truss and ancillary structure inside the L-Block.



14. Close up of wall supporting roof truss. Several of the trusses exhibit these horizontal/diagonal cracks in the wall at the ends.



15. The underside of one of the newer additions on the north side of the L-Block. The walls are cracked and covered with efflorescence. The beam reinforcement is exposed and rusting.



16. More inadequately covered and exposed reinforcement at the soffit of the floor slab. The repair attempt is inadequate.