





41. Stormwater drains inside the compound. Note broken gutter on kitchen roof.



43. Good cyclone washer fixings on the new maternity wing adjacent the L-Block.



44. Derelict buildings provide ready sources of flying debris.



42. Main stormwater outfall