

Photo HL-3: Cracks at corner of Boiler Room.




Photo HL-4: Base of some posts reinforced with angle iron.