

photo NO. 11 wall is cracked



photo NO 12 exp-joint is cracked



photo NO. 13 subsidence in the ground




photo NO. 14 destroyed brick wall




photo NO 15 pipe laying is differ