




Foto 2.- Columna localizada en la parte Norte de la edificación, mostrando falla por cortante [1].

Photo 2.- Column failed in shear located on the northern part of the structure [1].