

**4) Hotel El Presidente (actualmente Hotel Stouffer Presidente)**

Ubicado en la colindancia Sureste del Hotel Holiday Inn. Estructura de CR registrado con el número 11 en el informe del AIJ.

**Características de la edificación:** Estructura de CR de 11 niveles (Fotos 50 y 51).

**Características del daño por sismo:** Los muros de mampostería de fachada cuentan con un sinnúmero de pequeños agujeros con distribución aleatoria, que generó agrietamientos notables en los muros. En el interior se tienen referencias de daños estructurales, sin embargo la información no pudo ser confirmada.

**Características del método de refuerzo:** Se contactó al jefe de mantenimiento del hotel (ingeniero mecánico de profesión), el cual tiene ese puesto desde hace tres años. El ingeniero informó que aunque se haya rehabilitado la estructura posteriormente a los sismos de 1985, no existe ningún plano que lo indique. Los muros de fachada se repararon. Una vez cada seis meses se entrena al personal sobre qué hacer ante la incidencia de un fenómeno natural. No existe información disponible para los huéspedes del hotel sobre procedimientos, métodos, rutas de salida etc. para evacuación, únicamente existen para el caso de incendio.

**4) Hotel El Presidente (now Hotel Stouffer Presidente)**

Located in the southeast boundary of the Hotel Holiday Inn. An RC structure identified with number 11 on the AIJ report.

**Structural characteristics:** An RC structure with 11 stories (Photos 50 and 51).

**Seismic damage:** The facade masonry walls have a large number of small holes randomly distributed, which contributed to wall weakening and significant wall cracking. There was some reference to structural damage inside the hotel; however, this information was not confirmed.

**Repair and/or strengthening method:** During the September 1993 visit, the head of maintenance of the hotel (a mechanical engineer) was contacted. This engineer has held his position for three years. The engineer reported that the structure was indeed retrofitted after the 1985 earthquakes. There are no structural drawings to bear witness to this fact. The facade walls were repaired. A drill is enforced upon the staff every six months on what to do in case of a natural phenomenon. There is no information available for hotel guests on procedures, methods, exit routes, etc. There are only instructions in case of fire.




Foto 50.- Hotel El Presidente después de los sismos de 1985 [1].

Photo 50.- Hotel El Presidente after the 1985 earthquakes [1].