"Documento original en mal estado"



FIGURE 3 197. Typical office scene where items are stored in a loosely stacked manner. Photograph courtesy of Richard Miller and the National Science Foundation.




FIGURE 3.198. Damage to ad hoc storage. Photograph courtesy of Richard Miller and the National Science Foundation.




FIGURE 3.199 Failure of dynamically sensitive internal components of a control cabinet during biaxial seismic testing. Photograph courtesy of Wyle Laboratories Scientific Services and Systems Group.

262




FIGURE 3 200. Failure of hydraulic control module during biaxial veising. Photographic contress of Wyle Laboratories Scientific Services and Systems Group.




FIGURE 3.201 Fahore of equipment rack during biaxial seismic testing. Photograph courtesy of Wyle Laboratories Scientific Services and Systems Group.