

In Fig. 12 through 14 other damages of two storied earthen buildings are shown after the recent earthquakes in the city of Kiaton. These buildings have suffered several strong earthquakes. Most of them have not been repaired during the last 50 years.



FIG. 13

Old earthen building near the sea shore. The separation of the mortar is typical.



FIG. 14

A two storied earthen building, 100 years old. This building has suffered at least 3 strong earthquakes, while it was not repaired after the second one.