



Fig. 34 General view of the Olive View Medical Center.




Fig. 35 Overturning of files at basement and nonstructural damage of gypsum boards in roof.