



FIGURE 74.—Typical collapsed column in Hotel Terminal



FIGURE 75.—Collapsed second story in one unit of the Catholic Boys School in Guatemala City. Roofs were originally at the same level.