



*Figure 2-5 Debris, consisting of broken concrete and wood framing systems, generated by surge action*



*Figure 2-6 Undermining of concrete decks and floor slabs caused the failure of many unreinforced concrete structures.*