



*Figure 2-13 Interior view of breakaway wall blocked by air conditioning unit and support platform (see Figure 2-11). Electric and cooling lines were extended through the breakaway panel.*



*Figure 2-14 These breakaway panels functioned as designed. Note the loss of the air conditioning unit platform.*