

Photo 25 - The Utilities Block



Photo 26 - Access to the roof of the Utilities Block Note the uneven spacing of ladder rungs. This could lead to accidents.