



Photo 29 - Airconditioning Plant on the roof of the Utilities Block




Photo 30 - Airconditioning Plant on the roof of the Utilities Block  
Note the absence of holding-down bolt in spite of provision by manufacturer.